




Parts and Hardware List


Α	8x30mm	B M4x35mm	С	D	E M4x14mm
		ACCOUNTAGE OF THE PARTY OF THE			
	16 pcs	8 pcs	28 pcs	28 pcs	36 pcs
F		G	H M3x14mm	1	J
				0	
	4 pcs	8 pcs	8 pcs	6 pcs	2 pcs
K		L			
	\bigcirc				
	2 pcs	12 pcs			











Step 3

























Step 13





Step 15

HOW TO ADJUST THE HINGES TO ALIGN THE DOORS IF NEEDED.

